Iowa State University

Department of Mechanical Engineering Collegiate Design and Student Organization Shop

Laboratory Safety Examination

You must complete the following quiz and score a minimum of 80% to be allowed to work in the
Nuclear Engineering shop space. Students scoring less than 80% MUST retake the exam until a minimum
score of 80% is achieved. All guizzes must be signed and dated.

Exam Instructions: Match the "best" term on the right to complete the statement on the left. Some terms may be used more than once but not all terms are used in all sections.

By signing below, I acknowledge that I have read the shop safety documentation, and have been trained on each of the safety points listed.

Name (Clearly Printed):	
Signature:	
Signature.	
Date:	

Section 1, General:

1.	Long sleeves, long hair, and loose clothing should be to prevent being caught in moving or rotating machinery. Ties, loose sweaters, jackets and jewelry should not be worn in the shop areas.
2.	It is always dangerous to grab, wipe off, or otherwise remove metal chips with your
3.	Never leave a machine unattended while it is
4.	Small pieces of material that are to be drilled on a drill press should be held securely in a
5.	To avoid possible damage or injury, it is a good practice to ease up on the pressure about the time the drill the metal.
6.	It is dangerous to leave a in the chuck after installing or removing a drill or work piece.
7.	Immediately any unsafe condition or behavior to the shop supervisor.
8.	and/or OSHA specific personal safety protection equipment must be worn while working in the lab.
9.	When grinding or buffering a piece of material, always hold the work piece with $a(n)$
10.	For foot protection, are good safety apparel but not required.
11.	For operator protection, always verify that all are in place on the equipment before running.
12.	Immediately report all accidents and equipment problems to the nearest
13.	Due to danger from pressure and flying debris such as metal chips, never direct a(n) at yourself or another person.
14.	While (i) tools are overall more dangerous to handle, (ii) tools require more cutting effort and can cause accident during use.
15.	For a liquid spill use to clean up the liquid.
16.	When using a drill press make sure to use the proper speed when operating.

- A. Breaks Through
- B. Fire Alarm
- C. Firm Grip
- D. Gloves
- E. Spindle
- F. Bare Hands
- G. Hot
- H. Key
- I. On-Off Switch or Emergency Stop
- J. Report
- K. Absorbent
- L. Running
- M. Safety Glasses
- N. Steel Toe Boots
- O. Secured
- P. Vise Grips Or Clamps
- Q. Guards and Shields
- R. Shop Supervisor
- S. Air Hose or Air Gun
- T. (i) Dull; (ii) Sharp
- U. (i) Sharp; (ii) Dull
- V. Drill Press Vise

Section 1, General continued:

17. Do not approach someone from while they are operating a machine, it may startle them and cause an injury.	A. Clear
18. For safety reasons, one should never carry with exposed cutting edges in your pocket.	B. Gloves
	C. Behind
19. Tools like chisels and punches with mushroomed heads are dangerous because of the potential for	D. Flying Fragments
20. Make sure others are of the work area around the machine you	E. Clearly Label
intend to use before turning it on.	F. Running
21. Allow the to reach full speed before stepping into position to use the tool.	G. One-Eighth Inch
	(1/8")
22. One should NOT wear while using a grinder.	H. Chisel
23. The tool rest on a grinder should not be less than from the face of the wheel.	I. Ground
24. One should never grind on the surface of a grinding wheel.	J. Sharp tools
25. Do not try to force the by having multiple people stand on it.	K. Side
26. An example of misusing a tool would be using a hammer on a	L. Sheet Metal Shear
27. One should never leave a running tool unattended while it is	M. Rotating
28. Use the specified by a particular job and material.	N. Ventilation
29. Inspect three-pronged electrical plugs before use to make sure theisn't broken off.	O. Away From You
30. Do not use a ladder if working around electrical sources.	P. Correct Grinding Wheel
	Q. One-Fourth Inch
	(1/4")
	R. In Front of
	S. Grinder
	T. Screwdriver
	U. Metal