

**Certified**  
**Manufacturing**  
**Technologist**

**Practice Exam**

SOCIETY OF MANUFACTURING ENGINEERS



## *FOREWORD*

Certification is the formal recognition of an individual's skills, expertise, and comprehension of a specified body of knowledge. Obtaining certification in your field is a significant personal achievement that also demonstrates your commitment to continuing education.

This workbook is designed to direct your studies as you prepare to join the ranks of Certified Manufacturing Technologists. It is comprised of a list of references used to develop examination questions, a list of recommended reading, and problems like those found on the Certified Manufacturing Technologist Examination.

Questions or comments should be directed to:

Manufacturing Engineering Certification Institute  
Society of Manufacturing Engineers  
One SME Drive, PO Box 930  
Dearborn, MI 48121  
(313) 271-1500  
Fax: (313) 271-2861  
e-mail: [cert@sme.org](mailto:cert@sme.org)  
home page: <http://www.sme.org/certification>

The Manufacturing Engineering Certification Institute of the Society of Manufacturing Engineers (MECI/SME) was established in 1971 as a means of recognizing manufacturing engineers and technologists for their years of work experience and academic knowledge. MECI/SME's purpose: to provide additional credentials for manufacturing professionals and encourage continuing education.

SME first introduced certification in January 1972 with the Certified Manufacturing Engineer (CMfgE) program. The Certified Manufacturing Technologist (CMfgT) credential was implemented in 1976. Now, SME offers a third certification in the Certified Enterprise Integrator.

Copyright © 1999 Manufacturing Engineering Certification Institute of the Society of Manufacturing Engineers

## *ACKNOWLEDGEMENT*

MECI/SME would like to express its appreciation to Philip Rufe, CMfgE, for his technical contribution to this Practice Exam. His suggestions will help improve the study process for Manufacturing Technologist Examination applicants.

## ***TABLE OF CONTENTS***

### ***Section 1***

#### **Introduction**

What is a Manufacturing Technologist?

About the Certified Manufacturing Technologist Examination

Preparing for the Examination

Retaining Certification

### ***Section 2***

#### **Body of Knowledge**

### ***Section 3***

#### **Sample Problems**

### ***Section 4***

#### **Solutions**

### ***Section 5***

#### **References**

## *What is a Manufacturing Technologist?*

A Manufacturing Technologist is one who carries out manufacturing projects in a responsible manner, using proven techniques known by those who are technically trained in the field of manufacturing. A Manufacturing Technologist is capable of performing job assignments which may involve: working on design, development and implementation of engineering plans; drafting; the erection of manufacturing engineering equipment; estimating; inspection and testing of materials and components. In performing these functions, the candidate must apply sound knowledge and understanding of materials, manufacturing processes and people.

In carrying out these duties, the competent supervision of skilled craftsmen may be necessary. The techniques employed demand acquired experience and knowledge of manufacturing technology, combined with the ability to organize the details of a job using established practices.

A Manufacturing Technologist is competent in the fundamentals of manufacturing, including:

- Mathematics/Applied Science/ Materials
- Product/Process design
- Manufacturing Processes
- Production System and Equipment Design
- Automated Systems and Control
- Quality and Customer Service
- Manufacturing Management and Personal Effectiveness

The candidate must have a minimum of four years of education and/or manufacturing-related work experience. Full-time students who have completed two years of education in a manufacturing-related curriculum may pursue professional certification at the Technologist level.

## *About The Certified Manufacturing Technologist Examination*

The Certified Manufacturing Technologist Examination, also called the Fundamentals of Manufacturing Examination, relies strongly on proven principles, calculations, data-driven answers and industry-wide norms. The examination contains 130 multiple-choice questions. Three hours are allowed for completion of the exam.

The Certified Manufacturing Technologist Examination is based on the proven experience of recognized experts in the field. Questions were written following proven professional test development procedures and were evaluated numerous times to assure relevancy and fairness. Following every exam cycle, each question is reviewed to assess its accuracy and reliability. This repeated assessment helps to ensure that the exam is able to test what is expected of candidates in a fair and effective manner.

The Certified Manufacturing Technologist Examination draws questions from a wide range of topics. It is expected that individuals who meet the candidate eligibility requirements and successfully complete this examination will have the broad base to fit into many applications and organizations.

Experts from both industry and academia identified competencies most important for individuals who hoped to achieve success in manufacturing engineering. These competencies are listed in the Examination Body of Knowledge. **Note: NOT ALL OF THE TOPICS LISTED WILL NECESSARILY BE REPRESENTED ON THE EXAMINATION, as the examination is constructed as a sampling of the many topics covered in the Body of Knowledge.**

## *Preparing For The Examination*

The amount of time needed to prepare for the Certified Manufacturing Technologist Examination will depend largely upon your level of education and experience. The examination is designed for an individual with at least four years of education and/or manufacturing experience. Full-time students who have completed two years of education in a manufacturing-related curriculum may pursue the Certified Manufacturing Technologist exam.

SME's Certification Committee recommends the following tips to anyone preparing to take a certification examination:

- Prepare for the certification examination as you would for any professional test (i.e. bar or medical examinations).
- Review the Examination Body of Knowledge and compare it to your own knowledge and experience. Make a list of those areas not in your background.
- Focus much of your attention and effort on these topics as you study.
- Practice taking the examination using the sample problems in this practice exam or in the Fundamentals of Manufacturing Self-Assessment Program (available from SME Customer Service).
- Focus additional studies in those topics you missed on the sample problems.
- Study the *Fundamentals of Manufacturing* workbook (available from SME Customer Service).
- Participate in an examination review course, if one is available in your area.
- Join a study group of others taking the examination.
- Organize your reference materials prior to the examination by indexing particular information you expect you will need to access quickly.

All certification exams are open book, and candidates are permitted to bring reference materials into the exam room. A hand-held calculator is necessary; computers are NOT allowed. No sharing of materials or calculators is allowed. No cell phones are permitted, and beepers must be in a silent mode.

## *Retaining Certification*

Certified individuals need to recertify every three years to ensure their technical knowledge is kept up-to-date. This is done by accumulating sufficient recertification credits or by retaking and passing the examination. Credits are awarded for most educational activities, including in-plant training programs, part-time teaching, patents, and attendance at conferences, courses, clinics and expositions.



**Fundamentals of Manufacturing (CMfgT)  
Certification Exam**

**Body  
Of  
Knowledge**



**Certified Manufacturing Technologist (CMfgT)**  
**Body of Knowledge – Revised May 2001**

**Module 1. MATHEMATICS, APPLIED & ENGINEERING SCIENCES, & MATERIALS APPLICATION (16.3%)**

- 1.1 Mathematics
  - 1.1.1 Algebra
  - 1.1.2. Trigonometry
  - 1.1.3. Analytical Geometry
  - 1.1.4. Calculus
- 1. 2. Applied and Engineering Sciences
  - 1.2.1. Metrication/SI System
  - 1.2.2. Physics
  - 1.2.3. Chemistry
  - 1.2.4. Statics
  - 1.2.5. Dynamics
  - 1.2.6. Fluid Mechanics
  - 1.2.7. Thermodynamics/Heat Transfer
  - 1.2.8. Electrical Circuits/Electronics
- 1.3. Materials Application
  - 1.3.1. Metals (Properties and Applications)
  - 1.3.2. Plastics/Polymers (Properties and Applications)
  - 1.3.3. Composites (Properties and Applications)
  - 1.3.4. Ceramics (Properties and Applications)
  - 1.3.5. Fluids (Properties and Applications)

**Module 2. PRODUCT/PROCESS DESIGN & DEVELOPMENT (13.4%)**

- 2.1 Research and Development
  - 2.1.1. Product R&D
  - 2.1.2. Process R&D
  - 2.1.3. Market/Sales/Life Cycle Analysis
  - 2.1.4. Intellectual Property Protection
- 2.2 Design
  - 2.2.1. Design Management
  - 2.2.2. Concurrent Engineering
  - 2.2.3. Design for X (Mfg/Assy/Maint/etc)
  - 2.2.4. Drafting/Drawing/Engineering Graphics
  - 2.2.5. CAD/CAM/CAE Applications
  - 2.2.6. Simulation/Engineering Design Analysis
  - 2.2.7. Tolerance Analysis/GD&T
  - 2.2.8. Engineering Economics/Value Analysis
  - 2.2.9. Product Prototype Build and Test
  - 2.2.10. Process Development and Test

**Module 3. MANUFACTURING PROCESS APPLICATIONS & OPERATION (14.1%)**

- 3.1 Manufacturing Process Applications and Operation
  - 3.1.1. Material Removal Processes
  - 3.1.2. Fabrication Processes
  - 3.1.3. Hot and Cold Forming Processes
  - 3.1.4. Casting and Molding Processes
  - 3.1.5. Electrical/Electronics Mfg. Processes
  - 3.1.6. Heat Treatment Processes
  - 3.1.7. Joining, Welding, and Assembly Processes
  - 3.1.8. Finishing Processes
  - 3.1.9. Bulk and Continuous Flow Processes
  - 3.1.10. Material Handling/Packaging
  - 3.1.11. Hand Tool Use/Machine Operating

**Module 4. PRODUCTION SYSTEM and EQUIPMENT DESIGN/DEVELOPMENT (20.9%)**

- 4.1 Production System Design and Development
  - 4.1.1 Infrastructure/Plant Location Analysis
  - 4.1.2. Facility Planning/Plant Layout
  - 4.1.3. Process Planning
  - 4.1.4. Capacity Planning
  - 4.1.5. Production/Manufacturing System Design
  - 4.1.6. Process Documentation/Work Instructions
  - 4.1.7. Tool and Equipment Selection
  - 4.1.8. Process and Equipment Capability Analysis
  - 4.1.9. Cost Justification
  - 4.1.10 Production System Build/Test
  - 4.1.11. Human Factors, Ergonomics, and Safety
  - 4.1.12. Maintenance Systems
  - 4.1.13. Environmental Protection/Waste Management
- 4.2 Equipment/Tool Design and Development
  - 4.2.1. Cutting Tool Design
  - 4.2.2. Workholding Tool Design
  - 4.2.3. Die/Mold Design
  - 4.2.4. Gage Design
  - 4.2.5. Machine Design
  - 4.2.6. Power Systems (Mech/Elec/Fluid)
  - 4.2.7. Control Systems (Mech/Elec/Fluid)

**Module 5. AUTOMATED SYSTEMS and CONTROL (5.3%)**

- 5.1. Automated Systems and Control
  - 5.1.1. Automated Systems (Hard/Flexible)
  - 5.1.2. CNC/PLC/Computer Control
  - 5.1.3. CIM Systems
  - 5.1.4. Computer Systems and Networks
  - 5.1.5. Information Technology/Database Systems (MIS,etc.)
  - 5.1.6. Enterprise-wide Systems Integration (MES,ERP,etc.)

**Module 6. QUALITY and CUSTOMER SERVICE (13.0%)**

- 6.1. Quality and Customer Service
  - 6.1.1. Customer Focus (Research/Test/Satisfaction)
  - 6.1.2. Quality System and Standards (QS/ISO/CE Mark/etc)
  - 6.1.3. Probability and Statistics
  - 6.1.4. Statistical Control Methods (Sampling/Charting/etc)
  - 6.1.5. Problem Analysis & Solving (Fishbone/Pareto/FMEA/etc)
  - 6.1.6. Factor Analysis (DOE/Correlation/etc)
  - 6.1.7. Capability Analysis (Process/Equipment/etc)
  - 6.1.8. Inspection/Test/Validation
  - 6.1.9. Metrology
  - 6.1.10. Reliability Analysis
  - 6.1.11. System/Process/Continuous Improvement (BPR/kaizen,etc)
  - 6.1.12. Customer and Field Service

**Module 7. MANUFACTURING MANAGEMENT (10.8%)**

- 7.1. Manufacturing Management
  - 7.1.1. Strategic Planning/Global Competitiveness
  - 7.1.2. Organizational Design and Management
  - 7.1.3. Project Management
  - 7.1.4. Personnel Management Methods (x/y/team/matrix/etc)
  - 7.1.5. Human Behavior/Motivation/Leadership
  - 7.1.6. Labor Relations
  - 7.1.7. Education/Training
  - 7.1.8. Operations Research, Analysis, & Forecasting
  - 7.1.9. Production Organization Systems (agile/lean/mass/etc)
  - 7.1.10. Material and Resource Management/Logistics
  - 7.1.11. Accounting/Finance/Economics
  - 7.1.12. Business/Engineering Ethics and Social Responsibility
  - 7.1.13. Standards, Laws, and Regulations

**Module 8. PERSONAL EFFECTIVENESS (6.2%)**

- 8.1. Personal Effectiveness
  - 8.1.1. Interpersonal Skills (listening, courtesy, etc.)
  - 8.1.2. Negotiating & Conflict Management (persuasion, conflict resolution)
  - 8.1.3. Presentation Skills & Oral Communication (formal & informal)
  - 8.1.4. Written Communication Skills (reports, computer literacy)
  - 8.1.5. Innovation & Creativity (idea generation & acceptance)
  - 8.1.6. Learning & Knowledge Transfer (info research & sharing; education)

## SAMPLE PROBLEMS

1. Which of the following equations factors in  $a^3 - 3a^2b + 3ab^2 - b^3$  ?

- A.  $(a+b)^3$
- B.  $(a-b)^3$
- C.  $(a^2 - 2ab + b^2)(a+b)$
- D.  $(a^2 - 2ab - b^2)(a-b)$

2. What is the average of the sample listed below?

<u>Observation #</u>	<u>Measurement</u>
1	0.786 mm
2	0.793 mm
3	0.754 mm
4	0.779 mm
5	0.782 mm
6	0.786 mm
7	0.780 mm


- A. 0.779 mm
- B. 0.780 mm
- C. 0.781 mm
- D. 0.782 mm

3. What is the standard deviation of the sample listed below?

<u>Observation #</u>	<u>Measurement</u>
1	0.786 mm
2	0.793 mm
3	0.754 mm
4	0.779 mm
5	0.782 mm
6	0.786 mm
7	0.780 mm

- A. 0.00015 mm
- B. 0.0124 mm
- C. 0.780 mm
- D. 6.50 mm

4. Determine height (h) of the triangle and the length of side a.



- A.  $h = 7.07$  ft,  $a = 9.23$  ft
  - B.  $h = 6.70$  ft,  $a = 10.00$  ft
  - C.  $h = 7.07$  ft,  $a = 8.23$  ft
  - D.  $h = 6.73$  ft,  $a = 9.23$  ft
5. What is the radiant power of a laser that delivers 50 joules of energy in one millisecond?
- A.  $5.0 \times 10^3$  joules
  - B.  $5.0 \times 10^4$  joules
  - C.  $5.0 \times 10^3$  watts
  - D.  $5.0 \times 10^4$  watts


6. **What is the total resistance of the circuit if the resistance of the lamps are as follows:**

$$R1 = 8\Omega$$

$$R2 = 20\Omega$$

$$R3 = 30\Omega$$

$$R4 = 10\Omega$$




- A.  $3.24\Omega$   
B.  $30.00\Omega$   
C.  $54.80\Omega$   
D.  $68.00\Omega$
7. **The unit of electric current rate is:**
- A. voltage  
B. coulomb  
C. watt  
D. ampere
8. **An electrical transformer is a device used to:**
- A. increase or decrease voltage  
B. open and close an electric circuit  
C. provide over-current protection  
D. convert alternating current to direct current

9. When an electric motor is turned off, its speed decreases exponentially. The motor's initial speed is 1,000 rpm. Its speed will decrease by half every 4 seconds. How long after the motor is turned off does the speed slow down to 31.25 rpm.

A. 12 seconds  
B. 16 seconds  
C. 20 seconds  
D. 24 seconds


10. Three 1.5 volt dry cells connected in parallel will produce:



A. 1.5 volts  
B. 3.5 volts  
C. 4.0 volts  
D. 4.5 volts


11. A 100 lb block is pushed along a horizontal surface by force P. The coefficient of friction between the block and the horizontal surface is 0.4. Find the acceleration experienced by the block when the pushing force (P) is 75 lb.

A.  $0.444 \text{ ft/sec}^2$   
B.  $0.644 \text{ ft/sec}^2$   
C.  $3.824 \text{ ft/sec}^2$   
D.  $6.440 \text{ ft/sec}^2$






12. For the steel torsion member shown, only the smaller portion (2 inch diameter section) is hollow. The member experiences two 2000 in-lb torsional loads as shown. Find the torsional deflection (angle of twist) developed in the 340 inch long member. (Modulus of Elasticity = 30,000,000 psi, Shear Modulus of Elasticity = 12,000,000 psi).
- A. 0.0163 Rad  
 B. 0.0184 Rad  
 C. 0.0214 Rad  
 D. 0.0298 Rad



13. If the simple normal stress for the material in the member below is not to exceed 65,000 psi, find the maximum allowable load (P). (Ignore the stress concentration).




- A. 106,366 lb  
 B. 115,781 lb  
 C. 116,352 lb  
 D. 146,250 lb

14. **When a metal is referred to as “tough”, this means that the metal:**
- A. resists grinding
  - B. does not deform plastically but breaks into pieces when stressed
  - C. dulls tools almost immediately
  - D. resists being broken or deformed by mechanical shock forces
15. **When a metal is referred to as “hard”, this means:**
- A. the metal resists indentation, penetration, and scratching
  - B. the same thing as toughness
  - C. the metal is more ductile
  - D. the metal can deform plastically
16. **The critical temperature for any metal is the temperature:**
- A. at which the metal goes through a phase change
  - B. below which the metal loses its magnetic properties
  - C. below which the metal does not deform plastically but shatters
  - D. above which the metal melts
17. **Which of the following is the best engineering plastics material that has high tensile strength, high compressive strength, with minimal elongation to use for a product that will be injection molded?**
- A. polycarbonate
  - B. polystyrene
  - C. phenolic
  - D. epoxy
18. **The best process for making a kitchen drawer divider tray out of plastic sheets is:**
- A. pulforming
  - B. thermoforming (vacuum forming)
  - C. compression forming
  - D. blowmolding

19. **The method of presentation of an object utilizing conventional drafting practice is commonly referred to as:**
- A. orthographic projection
  - B. side projection
  - C. right projection
  - D. left side projection
20. **Which of the following organizations specifies standards for designing drafting?**
- A. Association for National Standards in Industry
  - B. Affiliated National Standards, Inc.
  - C. Association of National Societies in Industry
  - D. American National Standards Institute
21. **The principal CIM technology that begins a product design cycle is:**
- A. CAM
  - B. CAD
  - C. CAE
  - D. CAPP
22. **Tolerance is:**
- A. difference between mating parts
  - B. same as allowance
  - C. permissible deviation from a desired dimension
  - D. deviation between a drawing and the actual part produced
23. **A turning operation is to be done on a piece of alloy steel that has a diameter of 3.5 inches. If the depth of cut is set at 0.125 inches, the feed is set at 0.012 inches per revolution, and the recommended cutting speed using a carbide tool is 275 feet per minute, what rpm setting available on the machine should be used?**
- A. 264 rpm
  - B. 300 rpm
  - C. 420 rpm
  - D. 532 rpm

24. The following diagram shows a 10 inch peripheral milling cutter that is set to cut a piece of steel. If the depth of cut is 0.5 inches, how far must the tool travel until the tool is engaged at its full depth on the workpiece (center of tool is positioned over the edge)?




- A. 2.18 in.  
B. 3.11 in.  
C. 4.52 in.  
D. 4.75 in.
25. If the diameter of a milling cutter is 12 inches and the cutting speed is 90 fpm, what is the approximate number of revolutions per minute the machine should be set at?
- A. 30 rpm  
B. 45 rpm  
C. 60 rpm  
D. 4.75 rpm
26. The purpose of a riser in a mold is:
- A. to help raise the molder  
B. the same as a cope  
C. to enhance the draft  
D. to feed liquid metal into the body of the casting as it solidifies
27. Emulsified oils are:
- A. high in sulphur content  
B. oil and water mixtures used for both lubricating and cooling  
C. lubricating oils diluted with naphta, kerosene or other petroleum-base solvents  
D. oils that have degraded over time

28. A tapered bushing is 4 inches long. The diameter of one end should be 0.250 inch larger than the other end. The bushing is mounted on a 16 inch mandrel between centers and is turned with a taper attachment. What should be the setting of the taper attachment in inches per foot?
- A. 0.250 inch per foot  
 B. 0.375 inch per foot  
 C. 0.500 inch per foot  
 D. 0.750 inch per foot

29. The following diagram shows what type of tool wear?

- A. crater wear  
 B. flank wear  
 C. edge wear  
 D. relief wear



30. How much horsepower is needed for a drilling operation to produce a 1.25 inch hole in a workpiece made of cast iron with a hardness of 150 HB. The speed used for this operation is 900 rpm, the feed rate is 0.005 ipr and the unit power requirement is 1.0 hp/in<sup>3</sup>/min. Assume the machine is running at 80% efficiency.
- A. 0.4 HP  
 B. 0.7 HP  
 C. 4.0 HP  
 D. 7.0 HP
31. The most common type of locating pin designed to minimize contact area between the workpiece and the locating pin, thereby reducing the chances of sticking or jamming is known as?
- A. tertiary locator  
 B. fixture key  
 C. low limit pin  
 D. diamond pin

- 32. The simplest and least expensive type of clamping device used to retain the workpiece in a jig or fixture is known as a:**
- A. strap clamp
  - B. pipe clamp
  - C. "C" clamp
  - D. Jorgeson clamp
- 33. The portion of a technical report which is written: (1) to avoid technical details, (2) to succinctly present the summary and conclusions of a project or investigation and (3) especially to be read by management is called a:**
- A. precis
  - B. abstract
  - C. executive summary
  - D. management synopsis
- 34. OSHA inspections are almost always conducted:**
- A. after written notification
  - B. without prior notice
  - C. after a company has been operating for five years
  - D. on an annual basis
- 35. The Occupational Safety and Health Act places the legal obligation to comply on:**
- A. supervisors
  - B. employers
  - C. every employee
  - D. manufacturers in interstate commerce
- 36. If a manufacturing plant had 20 injuries and job-related illnesses during a period in which all employees worked a total of 800,000 hours, what would be the plant's total injury-illness rate based upon OSHA's current factor of hours worked per year by 100 employees?**
- A. 5.0
  - B. 5.2
  - C. 10.4
  - D. 15.0



- 37. A letter of transmittal is used:**
- A. to confirm receipt of a fax document
  - B. as an e-mail boilerplate
  - C. to accompany shipments to customers
  - D. to convey a report from one firm to another
- 38. What is the available production capacity per week of four automated machines working two eight-hour shifts per day, six days per week, with an average machine utilization rate of 90%?**
- A. 86 hours
  - B. 173 hours
  - C. 345 hours
  - D. 384 hours
- 39. The following data is available: labor and machine total cost is \$10.00/hr, operation time is 3 min/part, material cost is \$0.10/part. The total cost per part would be:**
- A. \$.40
  - B. \$.60
  - C. \$.75
  - D. \$30.10
- 40. The initial process through which labor unions and company officials meet to adjust conflicting perspectives and interests is known as:**
- A. mediation
  - B. arbitration
  - C. negotiation
  - D. collective bargaining
- 41. When using production flow analysis, which of the following criteria is the primary determinant of group membership.**
- A. tolerances
  - B. geometric attributes
  - C. functional attributes of the part
  - D. operation sequence and machine routing

- 42. The analysis of the aggregate production plan, or the master production schedule to determine if there is sufficient capacity at critical points in the production process, is best accomplished with:**
- A. Material Requirements Planning
  - B. Capacity Requirements Planning
  - C. Rough-Cut Planning
  - D. Manufacturing Resource Planning
- 43. An Ishikawa diagram can be used to:**
- A. graphically display the relationships between variables in a two-way factorial experiment
  - B. analyze the causal relationships between process variables that can affect the quality of the product
  - C. determine the loss function for a given set of quality characteristics
  - D. determine the capacity of a process
- 44. In statistical process control, the most common size for a sample subgroup is:**
- A. 5
  - B. 10
  - C. 10% of the group
  - D. 20% of the group
- 45. The term X-bar refers to the:**
- A. mode
  - B. range
  - C. mean
  - D. standard deviation
- 46. Point E on chart 1 indicates a period when:**
- A. the upper control limit was exceeded
  - B. quality was highest
  - C. the average process capability exceeded 0.0080
  - D. the upper tolerance limit was exceeded



# CHART 1

PART NAME (PRODUCT)															OPERATION (PROCESS)										PART NO.					CHART NO.				
OPERATOR					MACHINE					GAGE					SPECIFICATION LIMITS					UNIT OF MEASURE					ZERO EQUALS									
DATE																																		
TIME																																		
SAMPLE MEASUREMENT	1	6.5	7.5	7.5	6.0	7.0	6.0	7.5	6.0	6.5	6.0	8.0	8.5	7.0	6.5	9.0	7.5	7.5	6.5	6.0	5.0	6.0	8.0	6.5	6.5									
	2	7.0	8.5	8.0	7.0	7.5	7.0	8.0	7.0	8.0	7.0	7.5	7.5	7.0	7.0	8.0	8.0	7.0	6.5	6.0	5.5	8.0	6.5	6.0	7.0									
	3	6.5	7.5	8.0	7.0	7.5	8.0	6.5	8.0	8.5	6.0	9.0	8.5	7.5	8.5	8.0	7.5	8.5	6.0	8.5	6.5	6.5	6.5	6.5	6.5	7.0								
	4	6.5	8.5	7.0	7.5	8.5	7.5	7.5	7.5	8.5	8.0	5.0	6.5	7.5	7.5	8.5	8.0	7.0	7.0	6.5	6.0	8.0	6.5	6.5	6.0	6.0								
	5	8.5	6.5	7.5	6.5	8.0	7.0	7.0	7.5	7.5	6.5	8.0	7.0	7.0	6.0	8.5	6.5	8.0	6.0	7.0	6.5	8.0	7.5	6.5	7.0	6.5								
SUM	35	38.5	38	34	37.5	36.5	36.5	36	39	33.5	37.5	38	36	36.5	42	37.5	38	33.5	35	31	33	34.5	34	32	33									
AVERAGE	7.0	7.7	7.6	6.8	7.5	7.3	7.3	7.2	7.8	6.7	7.5	7.6	7.2	7.1	8.4	7.5	7.6	6.7	7.0	6.2	6.6	6.8	7.0	6.4	6.6									
RANGE	2.0	2.0	1.0	1.5	2.0	1.5	1.5	2.0	2.0	2.0	4.0	2.0	0.5	2.5	1.0	1.5	1.5	1.5	2.0	0.5	3.0	2.0	1.5	1.0	1.0									
NOTES																																		
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25									



**47. Line D in Chart 1 represents:**

- A. R-bar
- B. X
- C. X-bar
- D. R

**48. The Capability Index (Cp) is used to:**

- A. establish the tolerance for a given characteristic
- B. determine the accuracy of the equipment that will be used for a process
- C. calculate the control limits for X-Bar and R charts
- D. determine if a process in a state of control is able to consistently produce results that are within the required tolerances

**49. A ring gage is used to measure:**

- A. outside diameter
- B. roundness
- C. outside diameter and roundness
- D. integrity of a grinding wheel

**50. Snap gages are used to check:**

- A. profiles
- B. outside diameters
- C. diameters of holes
- C. surface roughness

**51. An inspector must precisely measure a machined, angled surface on a casting. Which of the following measuring devices would be an appropriate instrument for this application?**

- A. sine bars
- B. Vernier caliper
- C. telescopic gages
- D. sliding T-Bevel

**52. The buttons on a sine bar are 10.0000 inches apart on centers. The bar is to be rested on gage blocks at an angle of 30°. The difference in height between the two piles of gage blocks must be:**

- A. 0.866 in.
- B. 2.588 in.
- C. 5.000 in.
- D. 7.071 in.

**53. A 1" to 2" micrometer reads as follows: barrel reads .550 and the thimble reads 12. The reading is:**

- A. 0.552
- B. 0.562
- C. 1.552
- D. 1.562

**54. What would be the value A after evaluating the following arithmetic expression?**

$$A = \text{INT}(\text{SQRT}((2.0 * 3.0) + (4.0 * 4.0)))$$

- A. 5
- B. 5.0
- C. 7
- D. 7.0

**55. NC contouring is an example of:**





- A. continuous-path positioning
- B. point to point positioning
- C. absolute positioning
- E. incremental positioning

56. The following NC program will produce which of the in-cut tool paths below?

```

N1 G90 G00 X-2. Y2. Z2. S1000 T1 M06
N2 X2. Z.1
N3 G01 Z-.125 F8
N4 X8
N5 X5. Y5.
N6 G00 Z.1
N7 X8. Y8.
N9 G01 Z-.125 F8
N10 X2.
N11 G00 Z2.
N12 X0 Y0
N13 Z0 M30

```



- A. A
- B. B
- C. C
- D. D

57. **A CNC machine tool that defaults to “leading zero suppression” and is capable of three decimal place accuracy would interpret the number 12 as:**
- A. 0.012
  - B. 0.120
  - C. 1.200
  - D. 12.000
58. **On a cylindrical robot, which of the following is not a basic degree of freedom?**
- A. the rotation of the arm
  - B. the radial telescoping
  - C. the closing of the end effector
  - D. the left to right swivel of the wrist
59. **Which type of robotic power system should be selected for extremely quick and accurate assembly of small components?**
- A. mechanical
  - B. pneumatic
  - C. electrical
  - D. hydraulic

## SOLUTIONS

### Problem Statement

1. Which of the following equations factors in  $a^3 - 3a^2b + 3ab^2 - b^3$  ?

A.  $(a+b)^3$

**B.  $(a-b)^3$**

C.  $(a^2 - 2ab + b^2)(a+b)$

D.  $(a^2 - 2ab - b^2)(a-b)$

### Solution

$$(a-b)^3 = (a-b)(a-b)^2 = (a-b)(a^2 - 2ab + b^2) = a^3 - 3a^2b + 3ab^2 - b^3$$

**Answer is (B)  $(a-b)^3$**

## Problem Statement

2. What is the average of the sample listed below?

<u>Observation #</u>	<u>Measurement</u>
1	0.786 mm
2	0.793 mm
3	0.754 mm
4	0.779 mm
5	0.782 mm
6	0.786 mm
7	0.780 mm

- A. 0.779 mm
- B. 0.780 mm**
- C. 0.781 mm
- D. 0.782 mm

## Given

Sample measurements

## Find

Sample average

## Definitions

$\bar{x}$  = sample average  
n = sample size  
 $x_i$  = individual measurements

## Formula

$$\bar{x} = \frac{1}{n} \sum_{i=1}^n x_i$$

## Solution

$$\bar{x} = \frac{1}{n} \sum_{i=1}^n x_i = \frac{1}{7} (0.786\text{mm} + 0.793\text{mm} + 0.754\text{mm} + 0.779\text{mm} + 0.782\text{mm} + 0.786\text{mm} + 0.780\text{mm})$$

$$\bar{x} = \underline{0.780\text{mm}}$$

**Answer is (B) 0.780 mm**

Beyer, W.H. (Eds.). (1987). CRC Standard Mathematical Tables (28th ed.)  
Boca Raton FL: CRC Press.



### Problem Statement

3. What is the standard deviation of the sample listed below?

<u>Observation #</u>	<u>Measurement</u>
1	0.786 mm
2	0.793 mm
3	0.754 mm
4	0.779 mm
5	0.782 mm
6	0.786 mm
7	0.780 mm

- A. 0.00015 mm
- B. 0.0124 mm**
- C. 0.780 mm
- D. 6.50 mm

### Given

Sample measurements

### Definitions

s= sample standard deviation  
n= sample size  
 $x_i$ = individual measurements

$\bar{x}$  = sample average

### Formula

$$s = \sqrt{\frac{\sum_{i=1}^n (x_i - \bar{x})^2}{n-1}}$$

### Solution

$$s = [1/6 [(0.786\text{mm} - 0.780\text{mm})^2 + (0.793\text{mm} - 0.780\text{mm})^2 + (0.754\text{mm} - 0.780\text{mm})^2 + (0.779\text{mm} - 0.780\text{mm})^2 + (0.782\text{mm} - 0.780\text{mm})^2 + (0.786\text{mm} - 0.780\text{mm})^2 + (0.780\text{mm} - 0.780\text{mm})^2 ] ]^{1/2}$$


$$s = \underline{0.0124\text{mm}}$$

**Answer is (B) 0.0124 mm**

Beyer, W.H. (Eds.). (1987). CRC Standard Mathematical Tables (28th ed.)  
Boca Raton FL: CRC Press.

### Problem Statement

4. Determine height (h) of the triangle and the length of side a.



- A.  $h = 7.07 \text{ ft}$ ,  $a = 9.23 \text{ ft}$   
B.  $h = 6.70 \text{ ft}$ ,  $a = 10.00 \text{ ft}$   
C.  $h = 7.07 \text{ ft}$ ,  $a = 8.23 \text{ ft}$   
D.  $h = 6.73 \text{ ft}$ ,  $a = 9.23 \text{ ft}$

### Given

- $A = 45 \text{ deg}$   
 $B = 50 \text{ deg}$   
 $C = 180 - 95 = 85 \text{ deg}$   
 $b = 10 \text{ ft}$   
 $c = 13.15 \text{ ft}$

### Find

a and h

### Definitions

- a = side a  
h = height of the triangle

### Formulas

$$\text{Law of Sines} = \frac{a}{\sin A} = \frac{b}{\sin B} = \frac{c}{\sin C}$$

### Solution

$$\frac{a}{\sin 45} = \frac{10 \text{ ft}}{\sin 50} \quad a = 9.23 \text{ ft}$$

$$\cos\theta = \frac{\text{opp}}{\text{hyp}} = \frac{h}{10\text{ft}}$$

$$h = 10\text{ft} \cos 45$$

$$h = 7.07 \text{ ft}$$

**Answer is (A) h= 7.07 ft, a= 9.23 ft**

### **Problem Statement**

5. What is the radiant power of a laser that delivers 50 joules of energy in one millisecond?
- A.  $5.0 \times 10^3$  joules
  - B.  $5.0 \times 10^4$  joules
  - C.  $5.0 \times 10^3$  watts
  - D.  $5.0 \times 10^4$  watts**

### **Given**

Energy = 50 joules  
Time = 0.001 sec

### **Find**

Power delivered

### **Definition**

Power = work/unit time

### **Solution**

$$\text{Power} = \frac{\text{work}}{\text{unit time}} = \frac{\text{joules}}{\text{seconds}} = \frac{50 \text{ joules}}{0.001 \text{ sec}} = 5.0 \times 10^4 \text{ Watts}$$

**Answer is (D)  $5.0 \times 10^4$  watts**

### Problem Statement


6. What is the total resistance of the circuit if the resistance of the lamps are as follows:

$$R1 = 8\Omega$$

$$R2 = 20\Omega$$

$$R3 = 30\Omega$$

$$R4 = 10\Omega$$



A.  $3.24\Omega$

**B.  $30.00\Omega$**

C.  $54.80\Omega$

D.  $68.00\Omega$

### Given

$$R1 = 8\Omega$$

$$R2 = 20\Omega$$

$$R3 = 30\Omega$$

$$R4 = 10\Omega$$

### Find

Total circuit resistance

### Definitions

R= resistance

## Formulas

Resistors in parallel

$$R_{23} = \frac{R_1 R_2}{R_1 + R_2}$$


Resistors in series

$$R_{eq} = R_1 + R_2 + R_3$$

## Solution

R2 and R3 are in parallel and can be combined as follows.

$$R_{23} = \frac{R_1 R_2}{R_1 + R_2} = \frac{600\Omega}{50\Omega} = 12\Omega$$



Resistors in series

$$R_{eq} = R_1 + R_{23} + R_4 = 8\Omega + 12\Omega + 10\Omega = 30\Omega$$

**Answer is (B) 30Ω**

**Problem Statement**

7. The unit of electric current rate is:

- A. voltage
- B. coulomb
- C. watt
- D. ampere**

**Answer is (D) amperes**

Power = Watts

Voltage = Volts

Charge = Coulombs

Current rate = Amperes<sup>7</sup>

<sup>7</sup>Reprinted from Halliday, D., & Resnick, R., 1988. Fundamentals of Physics  
3rd ed. New York: John Wiley & Sons, Inc. Reproduced with permission.



### **Problem Statement**

8. An electrical transformer is a device used to:
- A. increase or decrease voltage**
  - B. open and close an electric circuit
  - C. provide over-current protection
  - D. convert alternating current to direct current

**Answer is (A) increase or decrease voltage**

An electric transformer is a device used to increase or decrease voltage. Step down transformers reduce voltage and increase current flow. Step up transformers increase the voltage and reduce the current flow.<sup>8</sup>

<sup>8</sup>Reprinted from Halliday, D., & Resnick, R., 1988. Fundamentals of Physics 3rd ed. New York: John Wiley & Sons, Inc. Reproduced with permission.

### Problem Statement

9. When an electric motor is turned off, its speed decreases exponentially. The motor's initial speed is 1,000 rpm. Its speed will decrease by half every 4 seconds. How long after the motor is turned off does the speed slow down to 31.25 rpm.
- A. 12 seconds  
B. 16 seconds  
**C. 20 seconds**  
D. 24 seconds

### Given

Initial speed = 1000 rpm  
Decreases speed by  $\frac{1}{2}$  every 4 seconds

### Definitions

C = initial value of y  
k = constant of proportionality  
t = time

### Formula

Exponential growth:  $y = Ce^{kt}$

### Solution

At time = 0,  $y = 1000$  rpm

$$1000 = Ce^{k(0)}$$
$$C = 1000$$

At time = 4 sec,  $y = 500$  rpm

$$500 = 1000e^{k(4)}$$
$$\ln(500/1000) = 4k$$
$$k = -0.1733$$


When  $y = 31.25$  rpm,  $t = ?$

$$31.25 = 1000e^{-0.1733t}$$
$$\ln(31.25/1000) = -0.1733t$$
$$t = 20 \text{ sec}$$

**Answer is (C) 20 seconds**

### Problem Statement

10. Three 1.5 volt dry cells connected in parallel will produce:



- A. 1.5 volts
- B. 3.5 volts
- C. 4.0 volts
- D. 4.5 volts

**Given**

Three 1.5 volt dry cells connected in parallel

**Find**

Total voltage

**Definitions**

$V_t$  = total voltage

$V$  = voltage of each dry cell

**Formula**

For dry cells in parallel

$$V_t = V$$

**Solution**


$$V_t = 1.5 \text{ Volts}$$

**Answer is (A) 1.5 volts**

### Problem Statement

11. A 100 lb block is pushed along a horizontal surface by force P. The coefficient of friction between the block and the horizontal surface is 0.4. Find the acceleration experienced by the block when the pushing force (P) is 75 lb.

- A.  $0.444 \text{ ft/sec}^2$   
B.  **$0.644 \text{ ft/sec}^2$**   
C.  $3.824 \text{ ft/sec}^2$   
D.  $6.440 \text{ ft/sec}^2$



### Find

Acceleration (a)

### Given

$$P = 75 \text{ lb}$$
$$W = 100 \text{ lb}$$
$$\mu = 0.4$$

### Definitions

$$F_f = \text{frictional force}$$
$$N = \text{normal force}$$
$$m = \text{mass}$$

### Formulas

$$F = ma$$

$$\Sigma F_x = F \cdot \cos\Theta - F_f = 0$$

$$\Sigma F_y = -W - (F \cdot \sin\Theta) + N = 0$$

**Solution**

$$(1) \quad \Sigma F_x = 75 \text{ lb} (4/5) - F_f$$

$$(2) \quad \Sigma F_y = -100 \text{ lb} - 75 \text{ lb}(3/5) + N = 0$$

$$(1) \quad N = 145 \text{ lb}$$

$$F_f = \mu N = 0.4(145 \text{ lb}) = 58 \text{ lb}$$

$$(1) \quad 75 \text{ lb} (4/5) - 58 \text{ lb} = 2 \text{ lb} \quad \text{net to the right}$$

$$(3) \quad F = ma \quad \text{or} \quad a = F/m$$

$$a = \frac{2 \text{ lb}}{100 \text{ lb} / 32.2 \text{ ft/s}^2}$$


$$a = 0.644 \text{ ft/s}^2$$

**Answer is (B) 0.644 ft/sec<sup>2</sup>**

## Problem Statement

12. For the steel torsion member shown, only the smaller portion (2 inch diameter section) is hollow. The member experiences two 2000 in-lb torsional loads as shown. Find the torsional deflection (angle of twist) developed in the 340 inch long member. (Modulus of Elasticity = 30,000,000 psi, Shear Modulus of Elasticity = 12,000,000 psi).

- A. 0.0163 Rad  
**B. 0.0184 Rad**  
C. 0.0214 Rad  
D. 0.0298 Rad



## Given

Two 2000 in-lb torsional loads  
The 2 inch diameter section is hollow  
Section one is 240 inches long and section two is 100 inches long  
 $G = 12,000,000$  psi

## Find

Torsional deflection

## Definitions

$\theta$  = angle of twist in radians  
 $T$  = internal resisting torque  
 $L$  = length  
 $G$  = shear modulus  
 $J$  = polar moment of inertia

## Formulas

$$\theta = \frac{TL}{JG}$$

$$J_{\text{solid shaft}} = \frac{\pi d^4}{32}$$

$$J_{\text{hollow shaft}} = \frac{\pi(d_o^4 - d_i^4)}{32}$$

## Steps

1. Cut the shaft where there is a change in load or geometry
2. Draw free body diagrams of each cut.
3. Calculate the internal resisting torque (T) for each free body diagram.
4. Calculate the angle of twist for each section.
5. Sum the angles for the total deflection.

## Solution

$$T_1 = 4000 \text{ in-lb}$$

$$T_2 = 2000 \text{ in-lb}$$

$$T_3 = 2000 \text{ in-lb}$$

$$\theta_1 = \frac{TL}{JG} = \frac{4000 \text{ lb} (100 \text{ in})}{[\pi(3 \text{ in}^4) / 32][12 \times 10^6 \text{ psi}]} = 0.00419 \text{ rad}$$

$$\theta_2 = \frac{TL}{JG} = \frac{2000 \text{ lb} (140 \text{ in})}{[\pi(3 \text{ in}^4) / 32][12 \times 10^6 \text{ psi}]} = 0.00293 \text{ rad}$$

$$\theta_3 = \frac{TL}{JG} = \frac{2000 \text{ lb} (100 \text{ in})}{[\pi(2 \text{ in}^4 - 1 \text{ in}^4) / 32][12 \times 10^6 \text{ psi}]} = 0.01132 \text{ rad}$$


$$\theta_T = \theta_1 + \theta_2 + \theta_3 = 0.0184 \text{ rad}$$

**Answer is (B) 0.0184 Rad**

### Problem Statement

13. If the simple normal stress for the material in the member below is not to exceed 65,000 psi, find the maximum allowable load (P). (Ignore the stress concentration).

- A. 106,366 lb
- B. 115,781 lb**
- C. 116,352 lb
- D. 146,250 lb



### Given

$$S_{\text{allowable}} = 65,000 \text{ psi}$$

Ignore stress concentration

### Find

Maximum allowable load, P

### Definitions

P = load  
S = stress

### Formula

$$\text{Stress} = \text{Load} / \text{Cross Sectional Area}$$

### Solution

$$\text{Load} = \text{Stress} \times \text{Cross Sectional Area}$$

$$P = 65,000 \text{ psi} [2.375 \text{ in} (0.750 \text{ in})]$$

$$P = 115,781 \text{ lb}$$

**Answer is (B) 115,781 lb**



### **Problem Statement**

14. When a metal is referred to as “tough”, this means that the metal:
- A. resists grinding
  - B. does not deform plastically but breaks into pieces when stressed
  - C. dulls tools almost immediately
  - D. resists being broken or deformed by mechanical shock forces.**

**Answer is (D) resist being broken or deformed by mechanical shock**

Toughness is a mechanical property which can be defined as a materials resistance to a sudden load or shock without failure.<sup>14</sup>

<sup>14</sup> Reprinted from DeGarmo P.E., Black, J.T., & Kohser, R.A., 1997, Materials and Processes in Manufacturing, 8<sup>th</sup> edition. New Jersey: Prentice Hall. Reproduced with permission.

### **Problem Statement**

15. When a metal is referred to as “hard”, this means:
- A. the metal resists indentation, penetration and scratching**
  - B. the same thing as toughness
  - C. the metal is more ductile
  - D. the metal can deform plastically

**The answer is (A) the metal resists indentation, penetration and scratching**

The harder a metal becomes the lower its toughness, ductility and plasticity.<sup>15</sup>

<sup>15</sup> Reprinted from DeGarmo P.E., Black, J.T., & Kohser, R.A., 1997, Materials and Processes in Manufacturing, 8<sup>th</sup> edition. New Jersey: Prentice Hall. Reproduced with permission.

### **Problem Statement**

16. The critical temperature for any metal is the temperature:
- A. at which the metal goes through a phase change**
  - B. below which the metal loses its magnetic properties
  - C. below which the metal does not deform plastically but shatters
  - D. above which the metal melts

**The answer is (A) at which the metal goes through a phase change**

Metals, being composed of phases, transform from one phase to another after passing through a specific temperature boundary. In the case of steel, austenite transforms into pearlite and ferrite after cooling through the critical temperature of 1330° F.<sup>16</sup>

<sup>16</sup> Reprinted from DeGarmo P.E., Black, J.T., & Kohser, R.A., 1997, Materials and Processes in Manufacturing, 8<sup>th</sup> edition. New Jersey: Prentice Hall. Reproduced with permission.

### **Problem Statement**

17. Which of the following is the best engineering plastics material that has high tensile strength, high compressive strength, with minimal elongation to use for a product that will be injection molded?
- A. polycarbonate
  - B. polystyrene**
  - C. phenolic
  - D. epoxy

**The answer is (B) polystyrene**

Polycarbonate and polystyrene are thermoplastics which are easier to injection mold than phenolics and epoxies which are thermosets. Polystyrene has a lower percent elongation than polycarbonate.<sup>17</sup>

<sup>17</sup> Reprinted from DeGarmo P.E., Black, J.T., & Kohser, R.A.,1997, Materials and Processes in Manufacturing, 8<sup>th</sup> edition. New Jersey: Prentice Hall. Reproduced with permission.

### **Problem Statement**

18. The best process for making a kitchen drawer divider tray out of plastic sheets is:
- A. pulforming
  - B. thermoforming (vacuum forming)**
  - C. compression forming
  - D. blowmolding

**Answer is (B) thermoforming (vacuum forming)**

Thermoforming is a good process for producing thin wall plastic parts with depressions or cavities. Pulforming is usually used for continuously reinforced parts. Compression forming is typically used for thermoset plastics and blowmolding is generally used for parts with an enclosed cavity such as a pop bottle.<sup>18</sup>

<sup>18</sup> Reprinted from DeGarmo P.E., Black, J.T., & Kohser, R.A., 1997, Materials and Processes in Manufacturing, 8<sup>th</sup> edition. New Jersey: Prentice Hall. Reproduced with permission.

### **Problem Statement**

19. The method of presentation of an object utilizing conventional drafting practice is commonly referred to as:

**A. orthographic projection**

B. side projection

C. right projection

D. left side projection

**Answer is (A) orthographic projection**

The method of presentation of an object utilizing conventional drafting practice is commonly referred to as orthographic projection. Side projection, right projection and left side projection are types of orthographic projection. The prefix ortho means at right angles.<sup>19</sup>

<sup>19</sup> Reprinted from Earle, J. H., 1994., Engineering Design Graphics , 8th ed., with permission from Addison Wesley Publishing Company.

### **Problem Statement**

20. Which of the following organizations specifies standards for designing drafting?
- A. Association for National Standards in Industry
  - B. Affiliated National Standards, Inc.
  - C. Association of National Societies in Industry
  - D. American National Standards Institute**

**Answer is (D) American National Standards Institute**

The American National Standards Institute (ANSI) specifies standards for design drafting. ANSI sets standard for drawing parts such as cap screws, machine screws, etc.<sup>20</sup>

<sup>20</sup> Reprinted from Earle, J. H., 1994, Engineering Design Graphics, 8th ed., with permission from Addison Wesley Publishing Company.

### **Problem Statement**

21. The principal CIM technology that begins a product design cycle is:
- A. CAM
  - B. CAD**
  - C. CAE
  - D. CAPP

**Answer is (B) CAD**

CAD or Computer-Aided Design is the principal CIM (Computer Integrated Manufacturing) technology that begins a product design cycle. Computer Aided Manufacturing, Computer Aided Engineering, and Computer Aided Process Planning are all integral parts of CIM, however a preliminary CAD design is the initial step.<sup>21</sup>

<sup>21</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988, Dearborn MI: Society of Manufacturing Engineers.



### **Problem Statement**

22. Tolerance is:

- A. difference between mating parts
- B. same as allowance
- C. permissible deviation from a desired dimension**
- D. deviation between a drawing and the actual part produced

**Answer is (C) permissible deviation from a desired dimension**

The total amount by which a dimension may vary or the difference between the limits is the tolerance.<sup>22</sup>

<sup>22</sup> Reprinted from Fundamentals of Manufacturing, pg. 115,1993, Dearborn, MI: Society of Manufacturing Engineers.

### Problem Statement

23. A turning operation is to be done on a piece of alloy steel that has a diameter of 3.5 inches. If the depth of cut is set at 0.125 inches, the feed is set at 0.012 inches per revolution, and the recommended cutting speed using a carbide tool is 275 feet per minute, what rpm setting available on the machine should be used?
- A. 264 rpm  
**B. 300 rpm**  
C. 420 rpm  
D. 532 rpm

### Given

Steel Diameter (d) = 3.5 in  
Cutting Depth = 0.125 in  
Feed Rate = 0.012 in/rev  
Cutting Speed (CS) = 275 fpm

### Find

Rpm setting

### Definitions

d= diameter  
CS = cutting speed of the metal

### Formula

$$RPM = \frac{12 (CS)}{\pi d}$$


### Solution

$$RPM = \frac{12 (CS)}{\pi d} = \frac{12 \text{ in/ft (275 ft/min)}}{\pi (3.5 \text{ in})/\text{rev}} = 300.1 \text{ rpm}$$

**Answer is (B) 300 rpm**

### Problem Statement

24. The following diagram shows a 10 inch peripheral milling cutter that is set to cut a piece of steel. If the depth of cut is 0.5 inches, how far must the tool travel until the tool is engaged at its full depth on the workpiece (center of tool is positioned over the edge)?



- A. 2.18 in.  
B. 3.11 in.  
C. 4.52 in.  
D. 4.75 in.

### Given

Cutter diameter = 10 in  
Depth of cut = 0.5 in

### Find

How far must the tool travel before it is to its full depth of cut.

### Definitions

$b$  = distance the cutter must travel before it is to its full depth of cut

### Formula

$$b = \sqrt{c^2 - a^2}$$

**Solution**

The distance the tool must travel,  $d$ , is the side of a right triangle. Using the Pythagorean theorem,  $c^2 = a^2 + b^2$ .

$$b = \sqrt{c^2 - a^2} = \sqrt{5\text{in}^2 - 4.5\text{in}^2} = 2.18\text{in}$$

**Answer is (A) 2.18 in**

### **Problem Statement**

25. If the diameter of a milling cutter is 12 inches and the cutting speed is 90 fpm, what is the approximate number of revolutions per minute the machine should be set at?

- A. 30 rpm**
- B. 45 rpm
- C. 60 rpm
- D. 4.75 rpm

### **Given**

Cutter diameter = 12 inches  
Cutting speed = 90 ft/min

### **Find**

rpm setting

### **Definitions**

CS = cutting speed of the metal  
d = cutter diameter

### **Formula**

$$RPM = \frac{12 (CS)}{\pi d}$$

### **Solution**

$$RPM = \frac{12 (CS)}{\pi d} = \frac{12 \text{ in/ft} (90 \text{ ft/min})}{\pi (12 \text{ in})/\text{rev}} = 28.7 \text{ rpm}$$

**Answer is (A) 30 rpm**

### **Problem Statement**

26. The purpose of a riser in a mold is:
- A. to help raise the mold
  - B. the same as a cope
  - C. to enhance the draft
  - D. to feed liquid metal into the body of the casting as it solidifies**

**Answer is (D) to feed liquid metal into the body of the casting as it solidifies**

The purpose of a riser in the gating system of a mold is to feed liquid metal into the body of the casting as it solidifies. Risers prevent shrinkage voids which occur where the casting solidifies.<sup>26</sup>

<sup>26</sup> Reprinted from DeGarmo P.E., Black, J.T., & Kohser, R.A., 1997, Materials and Processes in Manufacturing, 8<sup>th</sup> edition. New Jersey: Prentice Hall. Reproduced with permission.

### **Problem Statement**

27. Emulsified oils are:

A. high in sulphur content

**B. oil and water mixtures used for both lubricating and cooling**

C. lubricating oils diluted with naphta, kerosene or other petroleum-base solvents

D. oils that have degraded over time

**Answer is (B) oil and water mixtures used for both lubricating and cooling**


Emulsified oils are oil and water mixtures used for both lubrication and cooling. The oil provides lubrication and corrosion resistance and the water provides excellent cooling characteristics.<sup>27</sup>

<sup>27</sup> Reprinted from Oberg, E., Jones, F.D., & Holbrook, H.L., 1996. Machinery's Handbook, 25th ed. New York: Industrial Press, Inc. Used with permission.

### Problem Statement

28. A tapered bushing is 4 inches long. The diameter of one end should be 0.250 inch larger than the other end. The bushing is mounted on a 16 inch mandrel between centers and is turned with a taper attachment. What should be the setting of the taper attachment in inches per foot?
- A. 0.250 inch per foot  
B. 0.375 inch per foot  
C. 0.500 inch per foot  
**D. 0.750 inch per foot**

### Given



### Find

Taper setting in inches per foot

### Definitions

D1 = smaller diameter  
D2 = larger diameter  
L = part length

### Formula

$$\text{taper per foot} = \frac{D2 - D1}{L}$$

### Solution

$$\text{taper per foot} = \frac{D2 - D1}{L} = \frac{0.250\text{in}}{4\text{ in (1ft/12in)}} = 0.750\text{in}$$

**Answer is (D) 0.750 inches per foot**




**Problem Statement**

29. The following diagram shows what type of tool wear?

- A. crater wear**
- B. flank wear
- C. edge wear
- D. relief wear

**Answer is (A) crater wear**



The diagram shows crater wear.

Crater wear forms on the face of the tool and forms a short distance behind the cutting edge.<sup>29</sup>

<sup>29</sup> Reprinted from Oberg, E., Jones, F.D., & Holbrook, H.L., 1996, Machinery's Handbook, 25th ed. New York: Industrial Press, Inc. Used with permission.

### **Problem Statement**

30. How much horsepower is needed for a drilling operation to produce a 1.25 inch hole in a workpiece made of cast iron with a hardness of 150 HB. The speed used for this operation is 900 rpm, the feed rate is 0.005 ipr and the unit power requirement is 1.0 hp/in<sup>3</sup>/min. Assume the machine is running at 80% efficiency.
- A. 0.4 HP  
B. 0.7 HP  
C. 4.0 HP  
**D. 7.0 HP**

### **Given**

d= 1.25 in  
rpm = 900  
f<sub>r</sub>= 0.005 in/rev  
P= 1.0 hp/in<sup>3</sup>/min  
E= 80%  
Q = material removal rate

### **Find**

Horsepower required

### **Definitions**

d = drill diameter  
f<sub>r</sub> = feed rate  
P = unit horsepower  
E= efficiency  
Q = material removal rate  
n<sub>r</sub> = rpm

### **Formula**

$$Q = \frac{\pi}{4} d^2 f_r (n_r)$$

$$\text{hp} = \frac{QP}{E}$$

**Solution**

$$\text{hp} = \frac{QP}{E} = \frac{\left[ \frac{\pi(1.25 \text{ in})^2}{4} (0.005 \text{ in/min})(900 \text{ rpm}) \right] [1 \text{ hp/in}^3 / \text{min}]}{0.80} = 6.9 \text{ hp}$$

**Answer is (D) 7.0 HP**

### **Problem Statement**

31. The most common type of locating pin designed to minimize contact area between the workpiece and the locating pin, thereby reducing the chances of sticking or jamming is known as?
- A. tertiary locator
  - B. fixture key
  - C. low limit pin
  - D. diamond pin**

**Answer is (D) diamond pin**

The most common type of locating pin designed to minimize sticking and jamming by reducing the contact area between the workpiece and the locating pin is the diamond pin. The diamond pin, as its name indicates, is in the shape of a diamond to minimize the contact area.<sup>31</sup>

<sup>31</sup> Reprinted from Curtis, M.A., 1998, Tool Design for Manufacturing. Englewood Cliffs NJ: Prentice Hall.

### **Problem Statement**

32. The simplest and least expensive type of clamping device used to retain the workpiece in a jig or fixture is known as a:

- A. strap clamp**
- B. pipe clamp
- C. "C" clamp
- D. Jorgeson clamp

**Answer is (A) strap clamp**

The strap clamp is the simplest and least expensive type of clamping device used to retain the workpiece in a jig or fixture. The strap clamp is used in low-production applications and is available in a variety of configurations.<sup>32</sup>

<sup>32</sup> Reprinted from Curtis, M.A., 1998, Tool Design for Manufacturing. Englewood Cliffs NJ: Prentice Hall.

### **Problem Statement**

33. The portion of a technical report which is written: (1) to avoid technical details, (2) to succinctly present the summary and conclusions of a project or investigation and (3) especially to be read by management is called a:
- A. precis
  - B. abstract
  - C. executive summary**
  - D. management synopsis

**Answer is (C) executive summary**

The portion of a technical report which is written: (1) to avoid technical details, (2) to succinctly present the summary and conclusions of a project or investigation and (3) especially to be ready by management is called an executive summary. An executive summary gives the main points and basic details of the entire report. An abstract is a miniature version of the much longer report.<sup>33</sup>

<sup>33</sup> Reprinted from Pauley, S.E., & Riordan, D.G., 1990, Technical Report Writing Today, 4th ed. Boston: Houghton Mifflin Company. Reprinted with permission.

### **Problem Statement**

34. OSHA inspections are almost always conducted:
- A. after written notification
  - B. without prior notice**
  - C. after a company has been operating for five years
  - D. on an annual basis

**Answer is (B) without prior notice**

OSHA inspections are almost always conducted without prior notice. An employer representative and employee representative can accompany the compliance officer during the inspection.<sup>34</sup>

<sup>34</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.

### **Problem Statement**

35. The Occupational Safety and Health Act places the legal obligation to comply on:
- A. supervisors
  - B. employers**
  - C. every employee
  - D. manufacturers in interstate commerce

**Answer is (B) employers**

The Occupational Safety and Health Act places the legal obligation to comply on employers. Employers are obligated to provide employees with a workplace free from recognized hazards that are likely to cause death or serious physical harm to the employees.<sup>35</sup>

<sup>35</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.



### **Problem Statement**

36. If a manufacturing plant had 20 injuries and job-related illnesses during a period in which all employees worked a total of 800,000 hours, what would be the plant's total injury-illness rate based upon OSHA's current factor of hours worked per year by 100 employees?
- A. 5.0**  
B. 5.2  
C. 10.4  
D. 15.0

### **Given**

20 job related injuries and illnesses  
800,000 employee hours worked during that period

### **Find**

Plant's total injury-illness rate

### **Formula**

$$\frac{\text{hours worked by employees during a period}}{\text{work hours per year}} = \frac{\text{number of injuries during the period}}{\text{total injury - illness rate}}$$

### **Solution**

Work weeks per year = 52-2(vacation) = 50 weeks

Hours per year = 50 weeks per year x 40 hours per week) = 2000 hours/year

$$\frac{800,000}{200,000} = \frac{20}{x}$$

$$x = \frac{(20)(200,000)}{800,000} = 5.0$$

**Answer is (A) 5.0**

### **Problem Statement**

37. A letter of transmittal is used:
- A. to confirm receipt of a fax document
  - B. as an e-mail boilerplate
  - C. to accompany shipments to customers
  - D. to convey a report from one firm to another**

**Answer is (D) to convey a report from one firm to another**

A letter of transmittal is used to convey a report from one firm to another. Transmittal letters indicate the report enclosed, the date it was requested and a paragraph indicating the report's purpose and scope.<sup>37</sup>

<sup>37</sup> Reprinted from Pauley, S.E., & Riordan, D.G., 1990. Technical Report Writing Today, 4th ed. Boston: Houghton Mifflin Company. Reprinted with permission.

### **Problem Statement**

38. What is the available production capacity per week of four automated machines working two eight-hour shifts per day, six days per week, with an average machine utilization rate of 90%?
- A. 86 hours
  - B. 173 hours
  - C. 345 hours**
  - D. 384 hours

### **Given**

4 automated machines  
two 8 hour shifts per day  
six days per week  
90% average utilization rate

### **Find**

Total available production capacity per week

### **Formula**

Production capacity per week = Design Capacity x Utilization rate

### **Solution**

4 machines (8 hours/shift) (2 shifts/day) (6 days/week) (0.90) = 345.6 hours

**Answer is (C) 345 hours**

**Problem Statement**

39. The following data is available: labor and machine total cost is \$10.00/hr, operation time is 3 min/part, material cost is \$0.10/part. The total cost per part would be:

- A. \$.40
- B. \$.60**
- C. \$.75
- D. \$30.10

**Given**

labor and machine total cost = \$10/hr  
operation time = 3 min/part  
material cost = \$0.10/part

**Find**

Total cost per part

**Solution**

Total cost per part = \$10/hr (3 min/part) (1 hr/60min) + \$0.10 per part = \$0.60

**Answer is (B) \$.60**

### **Problem Statement**

40. The initial process through which labor unions and company officials meet to adjust conflicting perspectives and interests is known as:
- A. mediation
  - B. arbitration
  - C. negotiation**
  - D. collective bargaining

**Answer is (C) negotiation**

The initial process through which labor unions and company officials meet to adjust conflicting perspectives and interests is known as negotiation. Mediation is when an outside unbiased person helps both parties achieve an agreement. Arbitration is when an outside unbiased person or group develops an arbitrary agreement for both parties involved. Collective bargaining is the process where the union bargains for wages, benefits, etc., with management for all of the union membership.<sup>40</sup>

<sup>40</sup> Reprinted from Amrine, H.T., Ritchey, J.A., & Moodie, C.L., 1987.

Manufacturing Organization and Management. Englewood Cliffs NJ: Prentice-Hall. Reprinted with permission.

### **Problem Statement**

41. When using production flow analysis, which of the following criteria is the primary determinant of group membership.
- A. tolerances
  - B. geometric attributes
  - C. functional attributes of the part
  - D. operation sequence and machine routing**

**Answer is (D) operation sequence and machine routing**

When using production flow analysis, operation sequence and machine routing are the criteria for group membership. Production flow analysis is a methodology for grouping parts into families. Group technology decreases part proliferation, design time and equipment cost.<sup>41</sup>

<sup>41</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.

### **Problem Statement**

42. The analysis of the aggregate production plan, or the master production schedule to determine if there is sufficient capacity at critical points in the production process, is best accomplished with:
- A. Material Requirements Planning
  - B. Capacity Requirements Planning
  - C. Rough-Cut Planning**
  - D. Manufacturing Resource Planning

**Answer is (C) rough-cut planning**

Rough-cut planning analyzes the aggregate production plan or the master production schedule to determine if there is sufficient capacity at critical points in the production process. It tests the feasibility of the master schedule and gives an indication of loading levels for both personnel and machine groups involved.<sup>42</sup>

<sup>42</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.

### **Problem Statement**

43. An Ishikawa diagram can be used to:
- A. graphically display the relationships between variables in a two-way factorial experiment
  - B. analyze the causal relationships between process variables that can affect the quality of the product**
  - C. determine the loss function for a given set of quality characteristics
  - D. determine the capacity of a process

**Answer is (B) analyze the causal relationships between process variables that can affect the quality of the product**

An Ishikawa diagram can be used to analyze the causal relationships between process variables that can affect the quality of the product. This is typically called a cause-and-effect analysis. This diagram enables the analysis of an effect for causes by considering the many diverse and complex relationships that exist.<sup>43</sup>

<sup>43</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.



### **Problem Statement**

44. In statistical process control, the most common size for a sample subgroup is:
- A. 5**
  - B. 10
  - C. 10% of the group
  - D. 20% of the group

**Answer is (A) 5**

In statistical process control, the most common size for a sample subgroup is 5. Sample sizes from 2 to 20 can be used, however 5 is commonly used because of the relative ease of further computations. A sample size of 5 is usually large enough to detect small shifts in the mean along with ensuring a normal distribution for the sample means.<sup>44</sup>

<sup>44</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.

### **Problem Statement**

45. The term X-bar refers to the:
- A. mode
  - B. range
  - C. mean**
  - D. standard deviation

**Answer is (C) mean**

The mean shows the value that the measurements tend to cluster around. The arithmetic mean is often called the average value  $\bar{x}$  (called “x bar”).<sup>45</sup>

<sup>45</sup> Reprinted from Fundamentals of Manufacturing, pg. 124, 1993. Dearborn, MI: Society of Manufacturing Engineers.



**Problem Statement**

46. Point E on chart 1 indicates a period when:

- A. the upper control limit was exceeded**
- B. quality was highest
- C. the average process capability exceeded 0.0080
- D. the upper tolerance limit was exceeded

# CHART 1

															PART NO.					CHART NO.						
PART NAME (PRODUCT)										OPERATION (PROCESS)										SPECIFICATION LIMITS						
OPERATOR					MACHINE					GAGE					UNIT OF MEASURE					ZERO EQUALS						
DATE																										
TIME																										
SAMPLE MEASUREMENTS	1	6.5	7.5	7.5	6.0	7.0	6.0	7.5	6.0	6.5	6.0	8.0	8.5	7.0	6.5	9.0	7.5	7.5	7.5	6.5	6.0	5.0	6.0	8.0	6.5	6.5
	2	7.0	8.5	8.0	7.0	7.5	7.0	8.0	7.0	8.0	7.0	7.5	7.5	7.0	7.0	8.0	8.0	7.0	7.0	6.5	6.0	5.5	8.0	6.5	6.0	7.0
	3	6.5	7.5	8.0	7.0	7.5	8.0	6.5	8.0	8.5	6.0	9.0	8.5	7.5	8.5	8.0	7.5	8.5	6.0	8.5	6.5	6.5	6.5	6.5	6.5	7.0
	4	6.5	8.5	7.0	7.5	8.5	7.5	7.5	7.5	8.5	8.0	5.0	6.5	7.5	7.5	8.5	8.0	7.0	7.0	6.5	6.0	8.0	6.5	6.5	6.0	6.0
	5	8.5	6.5	7.5	6.5	8.0	7.0	7.0	7.5	7.5	6.5	8.0	7.0	7.0	6.0	8.5	6.5	8.0	6.0	7.0	6.5	8.0	7.5	6.5	7.0	6.5
SUM	35	38.5	38	34	37.5	36.5	36.5	36	39	33.5	37.5	38	36	36.5	42	37.5	38	33.5	35	31	33	34.5	34	32	33	
AVERAGE	7.0	7.7	7.6	6.8	7.5	7.3	7.3	7.2	7.8	6.7	7.5	7.6	7.2	7.1	8.4	7.5	7.6	6.7	7.0	6.2	6.6	6.8	7.0	6.4	6.6	
RANGE	2.0	2.0	1.0	1.5	2.0	1.5	1.5	2.0	2.0	2.0	4.0	2.0	0.5	2.5	1.0	1.5	1.5	1.5	2.0	0.5	3.0	2.0	1.5	1.0	1.0	
NOTES																										
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	



**Given**

Sample averages	Sample ranges
7.0	2.0
7.7	2.0
7.6	1.0
6.8	1.5
7.5	1.5
7.3	2.0
7.3	1.5
7.2	2.0
7.8	2.0
6.7	2.0
7.5	4.0
7.6	2.0
7.2	0.5
7.1	2.5
8.4	1.0
7.5	1.5
7.6	1.5
6.7	1.5
7.0	2.0
6.2	0.5
6.6	3.0
6.9	2.0
6.3	1.5
6.4	1.0
6.6	1.0

**Find**

UCL = Upper Control Limit

**Definitions**

X-bar bar = mean of the X-bars

R-bar = mean range

n = number of samples

A<sub>2</sub> = constant

### Formulas

$$\bar{x} = \frac{1}{n} \sum_{i=1}^n x$$

$$\bar{R} = \frac{1}{n} \sum_{i=1}^n R$$

$$UCL = \bar{x} + A_2(\bar{R})$$

### Solution

$$\bar{x} = \frac{1}{n} \sum_{i=1}^n x = 7.136$$

$$\bar{R} = \frac{1}{n} \sum_{i=1}^n R = 1.720$$

$$UCL = \bar{x} + A_2(\bar{R}) = 7.136 + 0.729(1.720) = 8.390$$

Sample average #15 (8.40) is greater than 8.390. Therefore, the upper control limit was exceeded.

**Answer is (A) the upper control limit was exceeded.**

### **Problem Statement**

47. Line D in Chart 1 represents:

- A. R-bar**
- B. X
- C. X-bar
- D. R

**Answer is (A) R-bar**

Line D in Chart 1 represents R bar. R bar is equal to 1.720 as calculated in problem 46.

R-bar is the mean or average of all the sample ranges.<sup>47</sup>

<sup>47</sup> Reprinted from Fundamentals of Manufacturing, 1993. Dearborn MI: Society of Manufacturing Engineers.

### **Problem Statement**

48. The Capability Index ( $C_p$ ) is used to:
- A. establish the tolerance for a given characteristic
  - B. determine the accuracy of the equipment that will be used for a process
  - C. calculate the control limits for X-Bar and R charts
  - D. determine if a process in a state of control is able to consistently produce results that are within the required tolerances**

**Answer is (D) determine if a process in a state of control is able to consistently produce results that are within the required tolerances**

The Capability Index ( $C_p$ ) is used to determine if a process in a state of control is able to consistently produce results that are within the required tolerances. The capability of a process can be viewed as the relationship between the specified limits for a dimension and the limits of the natural variability of the dimension.<sup>48</sup>

<sup>48</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.



### **Problem Statement**

49. A ring gage is used to measure:
- A. outside diameter
  - B. roundness
  - C. outside diameter and roundness**
  - D. integrity of a grinding wheel

**Answer is (C) outside diameter and roundness**

A ring gage is selected to functionally check the external diameters of a part for a combination of size and roundness. This functional check is performed with the employment of a Go ring and a separate No Go ring, which are ground to the high and low limits of the diameter in question, respectively. When a diameter is passed as good via inspection with ring gages, it is safe to assume that the diameter will fit its mating part at assembly. When roundness is not a major consideration, a snap gage would provide a less expensive alternative for checking the limits of external diameters.<sup>49</sup>

<sup>49</sup> Reprinted from Curtis, M.A., 1998. Tool Design for Manufacturing, pg. 142. Englewood Cliffs, NJ: Prentice Hall.

### **Problem Statement**

50. Snap gages are used to check:

- A. profiles
- B. outside diameters**
- C. diameters of holes
- D. surface roughness

**Answer is (B) outside diameters**

A snap gage is used for external dimensions such as the diameter of a shaft.<sup>50</sup>

<sup>50</sup> Reprinted from Fundamentals of Manufacturing, pg. 118, 1993. Dearborn; MI: Society of Manufacturing Engineers.

### **Problem Statement**

51. An inspector must precisely measure a machined, angled surface on a casting. Which of the following measuring devices would be an appropriate instrument for this application?

- A. sine bars**
- B. Vernier caliper
- C. telescopic gages
- D. sliding T-Bevel

**Answer is (A) sine bars**


An inspector must measure the angle of a beveled surface on a casting. Sine bars would be an appropriate measuring device for this inspection. The sine bar is very useful when measuring angles when the limit of accuracy is 5 minutes or less.<sup>52</sup>

<sup>52</sup> Reprinted from Oberg, E., Jones, F.D., & Holbrook, H.L., 1996. Machinery's Handbook 25th ed. New York: Industrial Press, Inc. Used with permission.

**Problem Statement**

52. The buttons on a sine bar are 10.0000 inches apart on centers. The bar is to be rested on gage blocks at an angle of  $30^\circ$ . The difference in height between the two piles of gage blocks must be:

- A. 0.866 in.
- B. 2.588 in.
- C. 5.000 in.**
- D. 7.071 in.



Given :

$$\Theta = 30^\circ$$

$$C = 10.0000$$

$$\text{SIN}\Theta = \frac{\text{OPP}}{\text{HYP}} = \frac{A}{C} = \frac{A}{10}$$

$$a = \text{SIN}30^\circ(10) = 0.5000(10.0000)$$

$$a = 5.000 \text{ inches}$$

**Answer is (C) 5.000 inches**


**Problem Statement**

53. A 1” to 2” micrometer reads as follows: barrel reads .550 and the thimble reads 12.  
The reading is:

- A. 0.552
- B. 0.562
- C. 1.552
- D. 1.562**

**Answer is (D) 1.562**

As illustrated below, the barrel reads .550 and the thimble indicates 0.012. Since this is a 1 in to 2 in micrometer, the diameter is 1.562.



**Problem Statement**

54. What would be the value A after evaluating the following arithmetic expression?

$$A = \text{INT}(\text{SQRT}((2.0 * 3.0) + (4.0 * 4.0)))$$

- A. 5
- B. 5.0
- C. 7
- D. 7.0

**Answer is (A) 5**

The value of A would be 5 after evaluating the expression. The square root of  $((2.0 * 3.0) + (4.0 * 4.0))$  is 4.690. The preceding INT command rounds the answer to the nearest integer which is 5.

### **Problem Statement**

55. NC contouring is an example of:

- A. continuous-path positioning**
- B. point to point positioning
- C. absolute positioning
- D. incremental positioning

**Answer is (A) continuous-path positioning**





NC contouring is an example of continuous path positioning. Continuous path positioning allows NC machines to perform contouring. Rate and direction of relative movement of machine members is under continuous numerical control. Point to point positioning moves the machine slides until a point is reached with no path control during the transition from one point to the next.<sup>56</sup>

<sup>56</sup> Reprinted from Tool and Manufacturing Engineers Handbook Desk Edition (Desk Edition), 1988. Dearborn, MI: Society of Manufacturing Engineers.

**Problem Statement**

56. The following NC program will produce which of the in-cut tool paths below?

```
N1 G90 G00 X-2. Y2. Z2. S1000 T1 M06  
N2 X2. Z.1  
N3 G01 Z-.125 F8  
N4 X8  
N5 X5. Y5.  
N6 G00 Z.1  
N7 X8. Y8.  
N9 G01 Z-.125 F8  
N10 X2.  
N11 G00 Z2.  
N12 X0 Y0  
N13 Z0 M30
```



- A. A
- B. B
- C. C
- D. D


**Answer is (A) shown below**



The NC program will generate the following tool path.

According to the program, absolute positioning is specified where the lower left edge of the work is X0, Y0 and the surface is Z0. The tool starts off the work piece at X-2, Y2, Z2. The tool then rapidly traverses over the work to X2, Z.1. The cutter feeds into the work to a depth of 0.125 in. and then proceeds in a straight line to X8. The cutter then proceeds to X5, Y5. It then retracts to 0.1 off the work and rapidly traverses to X8, Y8. The cutter then plunges down 0.125 into the work piece and then proceeds to X2.

A



### **Problem Statement**

57. A CNC machine tool that defaults to “leading zero suppression” and is capable of three decimal place accuracy would interpret the number 12 as:

- A. **0.012**
- B. 0.120
- C. 1.200
- D. 12.000

**Answer is (A) 0.012**

A CNC machine tool that defaults to “leading zero suppression” and is capable of three decimal place accuracy would interpret the number 12 as 0.012. Leading zero suppression eliminates the insignificant leading zeroes to the left of the significant digits.<sup>58</sup>

<sup>58</sup> Reprinted from Seamers, W.S., 1986. Computer Numerical Control: Concepts and Programming. Albany NY: Delmar Publishers. Reproduced by permission.

### **Problem Statement**

58. On a cylindrical robot, which of the following is not a basic degree of freedom?
- A. the rotation of the arm
  - B. the radial telescoping
  - C. the closing of the end effector**
  - D. the left to right swivel of the wrist

**Answer is (C) the closing of the end effector**

On a robot the closing of the end effector is not a basic degree of freedom. A degree of freedom is a joint linking two sections of a robot allowing freedom of motion. The base of the robot can move in the X and Y direction and twist accounting for 3 degrees of freedom. The wrist of the robot has pitch, roll, and yaw which account for another 3 degrees of freedom.<sup>59</sup>

<sup>59</sup> Reprinted from Tool and Manufacturing Engineers Handbook (Desk Edition), 1988. Dearborn MI: Society of Manufacturing Engineers.

### **Problem Statement**

59. Which type of robotic power system should be selected for extremely quick and accurate assembly of small components?
- A. mechanical
  - B. pneumatic
  - C. electrical**
  - D. hydraulic

**Answer is (C) electrical**

Electricity is the power system of choice for robot arms. It is clean, quiet, capable of fast moves, well understood, and requires little maintenance.<sup>60</sup>

<sup>60</sup> Reprinted from Fundamentals of Manufacturing, 1993. Dearborn, MI: Society of Manufacturing Engineers.

## Sample Problems Reference List

This section contains a list of references used for the sample problems.

1.            Advanced Manufacturing Technology, Goetsch, D.L., Albany NY: Delmar, 1990.
2.            Applied Statics and Strength of Materials 2nd ed., Spiegel, L., & Limbrunner, G.F., New York: Macmillan, 1991.
3.            Calculus 4th ed., Larson, R.E., Hostetler, R.P., & Edwards, B.E., Lexington, MA: D.C. Heath & Company, 1990.
4.            Computer Numerical Control: Concepts and Programming, Seamers, W.S., Albany, NY: Delmar, 1986, 1994.
5.            CRC Standard Mathematical Tables 28th ed., Beyer, W.H. (Eds.), Boca Raton, FL: CRC Press, 1987.
6.            Dictionary of Manufacturing Terms, R. Veilleux, Society of Manufacturing Engineers: Dearborn, MI, 1987.
7.            Engineering Design Graphics 8th ed., Earle, James H., New York: Addison Wesley Publishing Company, 1994.
8.            Fundamentals of Manufacturing, Dearborn, MI: Society of Manufacturing Engineers, 1993.
9.            Fundamentals of Physics 3rd ed., Halliday, D., & Resnick, R., New York: John Wiley & Sons, Inc., 1988.
10.           Machinery's Handbook 25th ed., Oberg, E., Jones, F.D., & Holbrook, H.L., New York: Industrial Press, Inc., 1996.
11.           Manufacturing Organization and Management, Amrine, H.T., Ritchey, J.A., & Moodie, C.L., Englewood Cliffs, NJ: Prentice-Hall, 1987, 1992.
12.           Materials and Processes in Manufacturing, 8<sup>th</sup> edition, DeGarmo P.E., Black, J.T., & Kohser, R.A., New Jersey: Prentice Hall, 1997.
13.           Problem Solving and Structured Programming in FORTRAN 77 4th ed., Koffman, E.B., & Friedman, F.L., New York: Addison-Wesley, 1990.

14. Production Operations and Management 6th ed., Chase, R.B., & Aquilino, N.J., Boston: Irwin, 1992.
15. Technical Report Writing Today 4th ed., Pauley, S.E., & Riordan, D.G., Boston: Houghton Mifflin, 1990.
16. Tool and Manufacturing Engineers Handbook Desk Edition, Dearborn, MI: Society of Manufacturing Engineers, 1988.
17. Tool Design for Manufacturing, Curtis, M.A., Englewood Cliffs, NJ: Prentice Hall, 1986, 1998.

## Additional References

This section contains a list of references covering exam content areas.

Since the examination covers a broad range of content, you may find the following three references to be most beneficial.

1. Fundamentals of Manufacturing, Dearborn, MI: Society of Manufacturing Engineers, 1993.
2. Fundamentals of Manufacturing Self-Assessment Program, Dearborn, MI: Society of Manufacturing Engineers, 1996.
3. Tool and Manufacturing Engineers Handbook (TMEH) Desk Edition, Dearborn, MI: Society of Manufacturing Engineers, 1988.

Below is a list of references used to develop items for the Fundamentals of Manufacturing Exam. Some references contain similar information so you may not need to consult each one.

### 1. Mathematics/Applied Science

Machinery's Handbook, 25<sup>th</sup> Edition, E. Oberg, F. Jones, H. Horton, Industrial Press, 1996.

### 2. Materials

Machinery's Handbook, 25<sup>th</sup> Edition, E. Oberg, F. Jones, H. Horton, Industrial Press, 1996.

Tool and Manufacturing Engineers Handbook, Desk Edition, SME, Dearborn, MI, 1988.

### 3. Product Design

Manufacturing Organization and Management 5<sup>th</sup> Edition, H. Amrine, J. Ritchie and C. Moodie, Prentice-Hall, Inc., Englewood Cliffs, NJ, 1992.

Tool and Manufacturing Engineers Handbook, Desk Edition, SME, Dearborn, MI, 1988.

### 4. Manufacturing Processes

Fundamentals of Tool Design, 4<sup>th</sup> Edition, SME, Dearborn, MI, 1998.

Machinery's Handbook, 25<sup>th</sup> Edition, E. Oberg, F. Jones, H. Horton, Industrial Press, 1996.

Manufacturing Organization and Management, 5<sup>th</sup> Edition, H. Amrine, J. Ritchie and C. Moodie, Prentice-Hall, Inc., Englewood Cliffs, NJ, 1992.

Tool and Manufacturing Engineers Handbook, Desk Edition, SME, Dearborn, MI, 1988.

Tool and Manufacturing Engineers Handbook, Volume 5, Manufacturing Management, SME, Dearborn, MI, 1988.

Tool and Manufacturing Engineers Handbook, Volume 4, Quality Control and Assembly, SME, Dearborn, MI, 1988.

## **5. Management and Economics**

Fundamentals of Tool Design, 4<sup>th</sup> Edition, SME, Dearborn, MI, 1998.

Manufacturing Organization and Management, 5<sup>th</sup> Edition, H. Amrine, J. Ritchie and C. Moodie, Prentice-Hall, Inc., Englewood Cliffs, NJ, 1992.

Manufacturing Technology, J. Lindbeck, M. Williams, and M. Wygant, Prentice-Hall, 1990.

Tool and Manufacturing Engineers Handbook, Desk Edition, SME, Dearborn, MI, 1988.

Tool and Manufacturing Engineers Handbook, Volume 5, Manufacturing Management, SME, Dearborn, MI, 1988.

## **6. Quality Control/Quality Assurance**

Statistical Quality Control, 6<sup>th</sup> Edition, E. Grant and R. Leavenworth, McGraw-Hill, New York, 1988.

Tool and Manufacturing Engineers Handbook, Volume 4, Quality Control and Assembly, SME, Dearborn, MI, 1988.

## **7. Computer Applications and Automation**

Machinery's Handbook, 25<sup>th</sup> Edition, E. Oberg, F. Jones, H. Horton, Industrial Press, 1996.